T 630.562.0300 F 630.562.0303 endtec.com



MOTOR FAILURE REPORT			
JOB INFORMATION			
ETI Job#: 00043336  Customer: ETI  Motor Mfg: AMK Arnold Muelle  Motor Type: SKT7-28-20-T00  Serial No: D346BD-451838  Equip Mfg: Arburg	er	Rpt Date: PO: Ref.: Cust Job #: Consignee PO: Equip Type: Equip SN:	Friday, July 3, 2020 CC CN 420A 195965
INSPECTION / TEST			
External Damage  Yes  No			
Parts Missing Yes V No			
Test Run Yes No			
Test Duration Dri	rive Used n/a		
Amplifier Alarms Cust. overcurrent ETI n/a			
COMPONENT CONDITION			
Stator Pass	Fail		
Rotor Pass	Fail Magnets loose a	nd slipping	
A side bearing journal  Pass	Fail		
B side bearing journal  Pass	Fail		
A side bearing bore  Pass	<b>F</b> ail		
B side bearing bore  Pass	<b>F</b> ail		
Output shaft	<b>Fail</b>		
Mounting flange	Fail		
Power connector Pass	Fail		
Encoder connector Pass	Fail		
Encoder Pass	Fail		
Bearing condition Pass	<b>✓</b> Fail		
CAUSE OF FAILURE			
✓ Contaminated	End of Life	Belt overtension	Alignment/Mechanical fit
Customer damage	Damaged by drive	Other Problem	No problem found



## NOTES

- 1. The primary cause of failure was a completely worn out encoder drive belt.
- 2. A secondary cause of failure was loose and slipping magnets on the magnet rotor.
- 3. The stator was badly contaminated with some kind of oil, but it had not caused any electrical failure.

